

NEW PRODUCT ANNOUNCEMENT

New intrinsically safe battery and carry solutions for APX6000/XE/Li and SRX2200 radios

OVERVIEW

Motorola Solutions is pleased to announce the new PMNN4547 intrinsically safe battery for the APX6000/XE/Li and SRX 2200 radios. This new battery features increased 3100mAh capacity and improved cold temperature performance. It is certified for use with intrinsically safe APX6000/XE and SRX2200 radios, per the statement below.

The SRX 2200 / APX 6000 / APX 6000XE / APX 6000Li Radio Models for HAZ LOC are listed by UL to standards: ANSI/TIA 4950-A and CAN/CSA C22.2 NO. 157-92; Classification Rating Class I, Division 1, Groups C, D; Class II, Division 1, Group E, F, G; Class III, Hazardous (Classified) Locations. ANSI/ISA 12.12.01-2015 and CAN/CSA C22.2 No.213-15; Class I, Division 2, Groups A, B, C, D; T3C. Tamb = - 25° C to +60° C. Intrinsically Safe (Sécurité Intrinsèque) when used with PMNN4547A.

The new PMNN4547 battery will require new plastic carry holsters and leather carry cases to accommodate a 3mm increase in thickness compared to the current NNTN8930 battery. Information regarding the new carry solutions is listed below.

Battery dimensions are 3.4" H x 2.3" W x 1.8" D (86 mm H x 59 mm W x 45 mm D) and nominal weight is 7 oz (200 grams).

LEGACY MODELS & REPLACEMENT SOLUTIONS

Description	Cancelled Model	Replacement Model	Used with
Plastic Carry Holster	PMLN5709	PMLN7901	APX6000, SRX2200
Plastic Carry Holster	PMLN5880	PMLN7902	APX6000XE
Leather Carry Case w/ Fixed Belt Loop	PMLN5658	PMLN7903	APX6000, SRX2200
Leather Carry Case w/ Swivel Belt Loop	PMLN5657	PMLN7904	APX6000, SRX2200
Leather Carry Case w/ Fixed Belt Loop	PMLN5876	PMLN7905	APX6000XE
Leather Carry Case w/ Swivel Belt Loop	PMLN5875	PMLN7906	APX6000XE



Please note, the replacement plastic carry holsters will accommodate all existing APX batteries, plus the new PMNN4547 battery. The replacement leather carry cases will accommodate all batteries the respective cancelled carry cases accommodated, plus the new PMNN4547 battery.

If you have questions regarding this notification, please contact your Motorola Solutions Account Representative.